

81 MAR 2008

Jeff Thompson
Vice President of Manufacturing
Advanced Heat Treat Corporation
2825 Midport Blvd.
Waterloo, IA 50703

Dear Mr. Thompson:

RE: Advanced Heat Treat Corporation
2839 Burton Ave.
Waterloo, IA
RCRA ID No. IAD056504186

On August 15, 2007, representatives of the U. S. Environmental Protection Agency (EPA) inspected your facility. The inspection was conducted under the authority of Section 3007 of the Resource Conservation and Recovery Act (RCRA).

A Letter of Warning/Section 3007 Information Request was issued February 7, 2008. I have reviewed your March 6, 2008, response to the Information Request and determined that it adequately addresses the violations listed in the Letter of Warning. Therefore, no further submittals are required at this time. Please note that EPA reserves its right to pursue appropriate enforcement actions, including penalties, for violations discovered as a result of this inspection, regardless of whether the violations were subsequently corrected.

I would like to remind you that your facility is responsible for maintaining compliance with all applicable hazardous waste regulations. If there are any questions regarding this matter, please contact me at (913) 551-7621 or buckner.edwin@epa.gov.

Sincerely,

Edwin G. Buckner, PE
Compliance Officer
RCRA Enforcement and State Programs Branch

cc: Chief, Iowa Geological Survey and Land Quality Bureau,
Iowa Department of Natural Resources

bcc: Gary Witkovski, ENSV

AWMD/RESP:cas:h:/EBUCKNER/AHTCLOC.DOC/032708

RESP

BUCKNER

03/ 26 /08

RESP

KOESTERER

03/ 27 /08

481415



RCRA



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 7
901 NORTH 5TH STREET
KANSAS CITY, KANSAS 66101

Jeff Thompson
Vice President of Manufacturing
Advanced Heat Treat Corporation
2825 Midport Blvd.
Waterloo, IA 50703

31 MAR 2008

Dear Mr. Thompson:

RE: Advanced Heat Treat Corporation
2839 Burton Ave.
Waterloo, IA
RCRA ID No. IAD056504186

On August 15, 2007, representatives of the U. S. Environmental Protection Agency (EPA) inspected your facility. The inspection was conducted under the authority of Section 3007 of the Resource Conservation and Recovery Act (RCRA).

A Letter of Warning/Section 3007 Information Request was issued February 7, 2008. I have reviewed your March 6, 2008, response to the Information Request and determined that it adequately addresses the violations listed in the Letter of Warning. Therefore, no further submittals are required at this time. Please note that EPA reserves its right to pursue appropriate enforcement actions, including penalties, for violations discovered as a result of this inspection, regardless of whether the violations were subsequently corrected.

I would like to remind you that your facility is responsible for maintaining compliance with all applicable hazardous waste regulations. If there are any questions regarding this matter, please contact me at (913) 551-7621 or buckner.edwin@epa.gov.

Sincerely,

A handwritten signature in black ink, appearing to read "Edwin G. Buckner".

Edwin G. Buckner, PE
Compliance Officer
RCRA Enforcement and State Programs Branch

cc: Chief, Iowa Geological Survey and Land Quality Bureau,
Iowa Department of Natural Resources